TIAL HAZARDOUS WASTE SITE SITE INSPECTION REPORT

SITE NUMBER (to be sealer ed by Hq 06 OK 5134

GENERAL INSTRUCTIONS: Complete Sections I and III through XV of this form as completely as possible. Then use the information on this form to develop a Tentative Disposition (Section II). File this form in its entirety in the regional Hazardous Waste Log File. Be sure to include all appropriate Supplemental Reports in the file. Submit a copy of the forms to: U.S. Environmental Pro-

tection Agency; Site Tracking Sys	tem; Hazardous Waste Enforcem	ent Tack Force			
	I. SITE IDEN		OKD		2566
A. SITE NAME		The second secon		P.O. Box 4	
King Fisher County Fee			est of Sec 3		
Okarche	1	OK	73762	King Fi	
G. SITE OPERATOR INFORMATION					
1. NAME				2. TELEPHON	E NUMBER
John McCarthy, Owner,	Marion Perdue, Presid	ent		(405) 26	3-7244
S. STREET	4. CITY -			S. STATE	6. ZIP CODE
P.O. Box 441	Okarch	e		OK	73762
H. REALTY OWNER INFORMATION (Il dillerent trom operator of alte)				
1. NAME				2. TELEPHON	E NUMBER
Same as I.G.1 above				1	
3. CITY				4. STATE	B. ZIP CODE
I. SITE DESCRIPTION The site	was a disposal pit f	rom 1987	109/ 100	nated appro	y 8 miles
	was a ursposar pre re-	(OVQ17)	10 1704, 100 Automobile	ateu appro Stires he	verage cans.*
West of King Fisher Co	ounty reed fards, Inc.	(0K017).	Automoulie	tires, oc	verage cans,
1. FEDERAL 2. STA		4. MUNICIPAL	X 8. PRIVA		
			22 01 1111	_	
	II. TENTATIVE DISPOSITION	(complete th	is section last)		
A. ESTIMATE DATE OF TENTATIVE					
DISPOSITION (mo., dey, & yr.)	1. HIGH	2. MEDIUM	3. LOW	X 4. NON	E
C. PREPARER INFORMATION					
1. NAME	$I \sim C > 1$	2. TELEPHON	13-15 15 25 107 15-15	4/30/85	gey, & yr.),
Hillol K. Ray Julo	May	(214) 74		4/30/63	
A. PRINCIPAL INSPECTOR INFORM	III. INSPECTION	INFORMATIC)N		
1. NAME	,,,,,,	2. TITLE			
Hillol K. Ray		FIT-Envir	onmental Eng	gineer	
Hillol K. Ray					E NO. (eres code & no.)
Ecology & Environment	Inc., 1509 Main St.,	Dallas,	TX 75201	(214) 742	2-6601
B. INSPECTION PARTICIPANTS				<u> </u>	
1. NAME	2. ORGAN	NIZATION		3. TEL	EPHONE NO.
				(21/) 7//	2.6601
Bill Park	Ecology & Environme	ent, Inc.		(214) 742	2-6601
		· · · · · · · · · · · · · · · · · · ·	100 0		
				 	
				1	
	VIEWED (companies officials as a final		·	1	
C. SITE REPRESENTATIVES INTER	2. TITLE & TELEPHONE NO.			. ADDRESS	
1. NAME	Yard Manager	King	Fisher Cou		ards, Inc.
Randy Hamilton	(405) 263-7244		Box 441, 0		
	Manager of Farming		CURT		
Art Meyer	(405) 263-7244		SUPERF FILE	UND	11.
			TILL		
					<u> </u>
en e grant e			AUG 1 0	1992	
			REORGAN	IZED	17000
	 			94	17666
((i)				1 100110 10111 11001	. KARK SANTA BUNG BUNG BUNG BUNG

EPA Form T2070-3 (10-79)

SO OF WASO

*A Form T2070-3 (10-79) PAGE 1 OF 10 Continue On Reverse
*construction/demolition debris, empty toxaphene containers, Tangolene-HD motor oil cans were disposed into the pit.

Continued From Front			
		PECTION INFORMATION (continued)	
. GENERATOR INFORMATION	1. TELEPHONE NO.	T	I was
(ing Fisher County	A. TELEPHONE NO.	P.O. Box 441	Automobile tires,
Teed Yards, Inc.	(405) 263-724	· Control of	peverage cans, const
eed laids, Inc.	(403) 203-124	4 Okarche, OK 73762	
•			ction/demolition det
	ļ		empty toxaphene
			containers (water ri
			Tangolene-HD motor o
TRANSPORTER/HAULER II	FORMATION		cans.
1. NAME	2. TELEPHONE NO.	3. ADDRESS	4.WASTE TYPE TRANSPORTED
Matt Siler (Decease	d) NA	NA	Same as III.D.4. abo
		1	
	l	,	
IP WASTE IN BRACESCO	N SITE AND ALCO CO.	I I I I I I I I I I I I I I I I I I I	ACH ITIES HEED FOR DISCOULT
		PED TO OTHER SITES, IDENTIFY OFF-SITE F	
1. NAME	2. TELEPHONE NO,	3. ADDR	E 33
IA.		1	
ın		 	
		1	
~			
DATE OF INSPECTION		ON I. ACCESS GAINED BY: (credentials must be	shown in all cases)
(14785 & yr.)	11:30 am	X 1. PERMISSION 2. WARR	ANT
WEATHER (describe)			
unny, 70°F, Light	SE winds, 5 to	8 mph	
		IV. SAMPLING INFORMATION	
Mark 'I' for the types of		icate where they have been sent e.g., region	al lab. other EPA lab. contractor.
etc. and estimate when th			
200	2. SAMPLE	· · · · · · · · · · · · · · · · · · ·	4. DATE
1. SAMPLE TYPE	TAKEN	S. SAMPLE SENT TO:	RESULTS_
	(merk 'X')		AVAILABLE
GROUNDWATER			
SURFACE WATER			j
. WASTE	1 1		
. AIR			1
- <u></u>			
RUNOFF			j j
SPILL			
. SOIL			
			
. VEGETATION		x	[
OTHER (epocity)			
] ,.],		
		o samples were taken during th	ne inspection.
FIELD MEASUREMENTS TA	KEN (e.g., redicactivity	explosivity, PH, etc.)	
-1.TYPE	2. LOCATI	N OF MEASUREMENTS	S.RESULTS
None_			
			
	eg 6.*e	1	
			
	×	· ·	
			
	1	1 '	

IV. SAMPLING INFORMATION (continued) C. PHOTOS 1. TYPE OF PHOTOS 2. PHOTOS IN CUSTODY OF: EPA Region 6, Dallas, TX (attached) A. GROUND D. AERIAL D. SITE MAPPED! See attached map, sketch and photographs X YES. SPECIFY LOCATION OF MAPS: E. COORDINATES 1. LATITUDE (deg.-min.-sec.) 2. LONGITUDE (deg.-min.-sec.) 35°39'47"N · 98°01'40"W V. SITE INFORMATION A. SITE STATUS 1. ACTIVE (Those industrial or X 2. INACTIVE (Those 3. OTHER(specify): municipal sites which are being used sites which no longer receive (Those sites that include such incidents like "midnight dumping" where no regular or continuing use of the site for waste disposal for waste treatment, storage, or disposal wastes.) on a continuing basis, even if infrehas occurred.) quently.) Since 1984 B. IS GENERATOR ON SITE! □ 1. NO 2. YES(epecify generator's four-digit SIC Code): C. AREA OF SITE (in acres) D. ARE THERE BUILDINGS ON THE SITE? Total=640 X 1. NO 2. YES(apecify): Disposal Pit=20'Lx15'Wx10'Deep) VI. CHARACTERIZATION OF SITE ACTIVITY Indicate the major site activity(ies) and details relating to each activity by marking 'X' in the appropriate boxes. A. TRANSPORTER, B. STORER C. TREATER D. DISPOSER I.RAIL 1. PILE 1. FILTRATION 1. LANDFILL 2. SHIP 2. SURFACE IMPOUNDMENT 2. INCINERATION 2. LANDFARM 3. OPEN DUMP B. BARGE S. DRUMS S. VOLUME REDUCTION 4. TRUCK 4. TANK, ABOVE GROUND 4. RECYCLING/RECOVERY 4. SURFACE IMPOUNDMENT S. PIPELINE S. MIDNIGHT DUMPING S. TANK, BELOW GROUND S. CHEM./PHYS./TREATMENT 6. OTHER (specify): 6. OTHER (specify): 6. BIOLOGICAL TREATMENT 6. INCINERATION 7. WASTE OIL REPROCESSING 7. UNDERGROUND INJECTION 8. OTHER (specify): B. SOLVENT RECOVERY 9. OTHER (specify): NA NA NA See Ii. Site Description E. SUPPLEMENTAL REPORTS: If the site falls within any of the categories listed below, Supplemental Reports must be completed. Indicate which Supplements! Reports you have filled out and attached to this for .. 4. SURFACE 2. INCINERATION 3. LANDFILL 5. DEEP WELL 1. STORAS. CHEM/BIO/ TREATMENT 7. LANDFARM 10. RECYCLOR/RECLAIMER 8. OPEN DUMP 9. TRANSPORTER VII. WASTE RELATED INFORMATION A. WASTE TYPE 1. LIQUID 3. SLUDGE 4. GAS X 2. SOLID B. WASTE CHARACTERISTICS 3. RADIOACTIVE 4. HIGHLY VOLATILE 1. CORROSIVE 2. IGNITABLE B. FLAMMABLE S. TOXIC 6. REACTIVE 7. INERT Automobile tires, beverage cans, construction/demolition debris, empty toxaphene containers and motor oil cans. 49. OTHER (epocity): Are records of wastes available? Specify items such as manifests, inventories, etc. below.

VIII. HAZARI	DESCRIPTION (co	ntinued)		
B. NON-WORKER INJURY/EXPOSURE		29		
•				
,			•	
· 4	7			
т				
			•	
÷				
C. WORKER INJURY/EXPOSURE		•		
<u>.</u>				
a a				
<u> </u>				
D. CONTAMINATION OF WATER SUPPLY				
r				
			25.	
•				
Ţ.				
		•		
· ·				
E. CONTAMINATION OF FOOD CHAIN				
			/	
F. CONTAMINATION OF GROUND WATER				İ
*				
* *				
		4		
* **				Ĭ
•				ľ
TTO CONTAMINATION OF SUBSACE WATER				
G. CONTAMINATION OF SURFACE WATER				
ζ.				•
e pre le silvino de la companio				
to the last of the things of the second				
				*
			ž.	

VIII. HAZARD DESCRIPTION (continued)		
H. DAMAGE TO FLORA/FAUNA		
,		
•		
•		
,	•	
~ <u>~</u> .		
. I. FISH KILL		
•		
J. CONTAMINATION OF AIR	w <u></u>	
,		0
· <u>.</u>		
K. NOTICEABLE ODORS	- · · · · ·	
- W. Welliebare seems		
	2	
		ł
L. CONTAMINATION OF SOIL		
L. CONTAMINATION OF SOIL		
i .		
	Ŷ	
· ·		
M. PROPERTY DAMAGE	 	
and the carry primary		
		•
,		
•		

	III. HAZARD DESCRIPTION (continued)	
N. FIRE OR EXPLOSION	** ***********************************	,	
ŀ			
· ·			
. 8			· •
			*
			* '
<u>-</u> " ≟ , ,			
O. SPILLS/LEAKING CONTAINERS/RUN	OFF/STANDING LIQUID		
			Ì
			Ì
P. SEWER, STORM DRAIN PROBLEMS	· · · · · · · · · · · · · · · · · · ·		
L_J JEWER, BIORM UKAIR PROBLEMS			
	· .		
		5	
Q. EROSION PROBLEMS		-	
4. ENGOINE PRODUCES			
•			
Ī			
I			
1			
R. INADEQUATE SECURITY			
**			1
			Ì
i e			
[•			
ſ			
			
S. INCOMPATIBLE WASTES			
· ·	9		
			İ
I		8	
fytt til lækker			-
			1
I	31 P		
Ī			
,			

		VЩ. HAZARD DESC	CRIPTION (continued)	-		
T. MIDNIGHT DUMPING						
			9			
·						
- L.						
			8			
U. OTHER (epocity): Duri	ng the	reconnaissanc	e inspection on	Anri	1 4. 1985. no	evidence of
surface run off or haz			-			site is
located in a very remo						
is significantly small						
to Mr. Art Meyer, Mana						
rinsed with water at "						
the above, the FIT rec						
,	· · · · · · · · · · · · · · · · · · ·				.,	
·						
*						
	IX. F	POPULATION DIREC	TLY AFFECTED BY SI	TE		
			C. APPROX. NO. OF PEO		D. APPROX. NO.	E. DISTANCE
A. LOCATION OF POPULATION		APPROX. NO.	AFFECTED WITHIN	PLE	OF BUILDINGS	TO SITE
	OF PE	OPLE AFFECTED	UNIT AREA		AFFECTED	(epecity units)
1. IN RESIDENTIAL AREAS		25	25		_	1 -41-
1. IN RESIDENTIAL AREAS		25	25		5	½ mile
2. IN COMMERCIAL OR INDUSTRIAL AREAS			1			_
OR INDUSTRIAL AREAS		10	10		2-3	½ mile
IN PUBLICLY						
3. TRAVELLED AREAS		_50	50		County Road	nile _
4. PUBLIC USE AREAS (parke, echoole, etc.)		^			,	, , ,
(part) tensors, siery		0	0		0	½ mile
A. DEPTHITO GROUNDWATER speci	for smilt)	X, WATER AND IB. DIRECTION OF FL	D HYDROLOGICAL DAT		ROUNDWATER USE IN	VICINITY
20-25 feet	.,					
D. POTENTIAL YIELD OF AQUIFER		North E. DISTANCE TO DRI	NKING WATER SUPPLY	F. D	rrigation, cat	IG WATER SUPPL
Less than 25 GPM		(epecity unit of mea 15 mile	saure)		SE	
G. TYPE OF DRINKING WATER SUP	PLY	15 11116	<u> </u>	L	OE.	
	2. COMMU	INITY (apecify town):	Piedmont, OK			*
<18 CONNECTIONS	> 18 CC	ONNECTIONS -	rredmont, or			
D. SURFACE WATER	4. WELL					

PAGE 8 OF 10

Continue On Page 9


EPA Form T2070-3 (10-79)


		X. WATER AND HYDROLOGICAL DA	TA (c	ontinued)			
H. LIST ALL DRIN	IKING WATER WEL	LS WITHIN A 1/4 MILE RADIUS OF SITE					
1. WELL	2. DEPTH (epecify unit)	3. LOCATION (proximity to population/	bulldi	ng»)	NON-COM- MUNITY (merk 'X')	COMMUN- ITY (mark 'Z')	
Mr. Meyer's Well	45'	t mile West from the dispose	al ŗ	oit	Х	,	
.4				:			
				:	† ·		
I. RECEIVING WAT	TER		- 7.	ំ ្ង	}	-	
1. NAME Uncle Joh	nn Crook	2. SEWERS X 3. STR	EAMS	/RIVERS			
Uncie Jon	III CLEEK	4. LAKES/RESERVOIRS B. OTH	ER(e	pecify):			
6. SPECIFY USE	AND CLASSIFICAT	TION OF RECEIVING WATERS	_ ,				
Primary w		isheries, agriculture, M & I o	2001	ing, secondary red	creation	and	
		XI. SOIL AND VEGITATION	DATI				
LOCATION OF SIT	TE IS IN: NA			·			
	FAULT ZONE	B. KARST ZONE	00 YE	EAR FLOOD PLAIN	D. WETLAND	•	
E. A REGUL	ATED FLOODWAY	F, CRITICAL HABITAT G. R	≀ECH	ARGE ZONE OR SOLE SOUR	CE AQUIFER		
	 	XII. TYPE OF GEOLOGICAL MATERIA	L OI	BSERVED			
Mark 'X' to indic	Mark 'X' to indicate the type(s) of geological material observed and specify where necessary, the component parts.						
X A. CVERBUR	RDEN X	B. BEDROCK (epecify below)	X x.	C. OTHER (epoc	cify below)		
1. SAND	. X D	Ouncan sandstone	Х	Sandy loam soils			
2. CLAY	x		х	Sandy clay loam	soils		
3. GRAVEL			'				
		XIII. SOIL PERMEABILIT	<u>Y</u>		·		
A. UNKNOWN D. MODERAT	TE (10 to .1 cm/sec.	B. VERY HIGH (100,000 to 1000 cm/se) E. LOW (.1 to .001 cm/sec.)	·c.)	C. HIGH (1000 to 10 cm		PC•)	
G. RECHARGE AR		COMMENTS:					
H. DISCHARGE AF	REA	COMMENTS				1	
I. SLOPE	<u></u>	V march 10.			 	 	
1. ESTIMATE % O	F SLOPE 2. S	SPECIFY DIRECTION OF SLOPE, CONDITION O	F SL	OPE, ETC.			
0-1% J. OTHER GEOLO	GICAL DATA	NE "-					
Duncan sand	dstone is a	fine grained sandstone with s a is 100 feet and more.	ome	mudstone conglome	rate and	shale;	
		e de la companya de la companya de la companya de la companya de la companya de la companya de la companya de La companya de la co					

Continued Fi	rom Front							
			XIV. PERMIT IN					
List all app	licable permits h	eld by the site and	provide the related i	nformation.	1	F. IN	COMPLI	ANCE
A. PER	A. PERMIT TYPE	B. ISSUING	C. PERMIT	D. DATE ISSUED	E. EXPIRATION DATE	(merk 'X')		
(O.B.,RCRA,SI	ete,NPDES,etc.)	AGENCY	NUMBER	(mo.,day,&yr.)	(mo.,dey,&yr.)	YES	NO	S. UN-
None		1				,		Ī
			***					+
·								
<u> </u>							-	┼──
			· · · · · · · · · · · · · · · · · · ·					
X NONE		XV. PAST	REGULATORY OR E	NFORCEMENT AC	TIONS			
(
NOTE: Ba								

SURFACE IMPS ADMENTS SITE INSPECT (Supplemental Report)	TION REPORT	Answer and Explain as Necessary.
1. TYPE OF IMPOUNDMENT		· ····································
Clay	,	· ·
2. STABILITY/CONDITION OF EMBANKMENTS	u .	
Excellent		
3. EVIDENCE OF SITE INSTABILITY (Erosion, Settling, Sink Holes, etc.)		
TES X NO		
4. EVIDENCE OF DISPOSAL OF IGNITABLE OR REACTIVE WASTE		
5. ONLY COMPATIBLE WASTES ARE STORED OR DISPOSED OF IN THE	IMPOUNDMENT	
Y YES NO	E	
6. RECORDS CHECKED FOR CONTENTS AND LOCATION OF EACH SUR	FACE IMPOUNDMENT	
☐ YES ☐ NO No records kept		
7. IMPOUNDMENT HAS LINER SYSTEM	7a. INTEGRITY OF LINER SYSTEM	CHECKED
₩ YES NO In situ clay	TES NO NA	,
7b. FINDINGS	<u> </u>	
NA 8. SOIL STRUCTURE AND SUBSTRUCTURE		
Process of the control of the contro		AN 100
Sand, clay, Duncan Sandstone, Sandy Loam s	oils, Sandy clay Loam s	oils.
9. MONITORING WELLS		
YES X NO	<u> </u>	
10. LENGTH, WIDTH, AND DEPTH	10'	
20	10	· · · · · · · · · · · · · · · · · · ·
11. CALCULATED VOLUMETRIC CAPACITY (approx) 3000 cubic feet		
12. PERCENT OF CAPACITY REMAINING		
33%		
13. ESTIMATE FREEBOARD	-	
3-5 feet		
14. SOLIDS DEPOSITION		
□ YE5 □ NO		
15. DREDGING DISPOSAL METHOD		
NA		
16. OTHER EQUIPMENT		
NA		
·		
		¥
		<u>-</u>
į (
, •		•
		•
P .		
4		
ļ	•	
EDA Esta Table 20 (10 de)		
EPA Form T2070-3C (10-79)		

1.	Name, address and phone number of resident (include county and zip code)
	Mr. Art Meyer, Manager of Farming
	King Fisher County Feed Yards, Inc.
	P.O. Box 441, Okarche, OK 73762
	Telephone: (405) 263-7244 County: King Fisher
2.	Date well was dugEarly 1975
3.	Depth of well 45 feet
4.	Depth to static water20 feet
5.	Is the well cased? Yes <u>x</u> No
	If so, to what depth? All the way to 45'
	What type of casing is used?PVC
6.	Is well screened? Yes x No
7.	How much is the well pumped? (Only for residential use or for use in watering livestock?)
8.	Any other pertinent information? None







PHOTOS 1, 2, 3

Photographer / Witness BILL PARKS/HILLOL RAY Date / Time / Direction 4-4-85/1145/N Comments: PANORAMA OF THE DISPOSAL PIT & THE TYPE OF MATERIALS DISPOSED, WITH RAIN WATER IN FOREGROUND. THE LABEL READS AS TANGOLENE - HD MOTOR OIL.

OKARCHE OKLAHOMA 73762

WEST

SEC 33, TISN, RGW



N

WEST

OKARCHE



Photographer / Witness BILL PARKS / HILLOL RAY Date / Time / Direction 4-4-85/1200/NE Comments: OFF-SITE WATER WELL OF MR. ART MEYER, MANAGER OF FARMING, KINGFISHER COUNTY FEED YARDS, INC.